

Photograph showing existing fixings



Photograph showing existing fixings and damage to the wood block floor due to relocation

Note: Plans and labels are to normal liturgical orientation

Legend

